



# American Resistance Party

How long will you wear the chains of your Masters?

Contact: Edward C. Noonan  
Tel: 530-777-3474  
Email: [ednoonan7@gmail.com](mailto:ednoonan7@gmail.com)  
Email: [americanresistanceparty@mail.com](mailto:americanresistanceparty@mail.com)  
<http://www.americanresistanceparty.org>

**FOR IMMEDIATE RELEASE  
ACTION ALERT**

**JERRY MOONBEAM BROWN  
Owns 2017 Oroville Dam Crisis**

2/13/16 – **EDWARD C NOONAN, Former 2012 & 2016 Presidential Candidate alert:**

I was in the evacuation of the 2017 Oroville Dam crisis. And this crisis has made wikipedia already. See:

[https://en.wikipedia.org/wiki/2017\\_Oroville\\_Dam\\_crisis](https://en.wikipedia.org/wiki/2017_Oroville_Dam_crisis)

There is the original wikipedia summary of the dam at:

[https://en.wikipedia.org/wiki/Oroville\\_Dam](https://en.wikipedia.org/wiki/Oroville_Dam)

I quote the following from the Wikipedia article:

## **2005 dam re-licensing**

*On October 17, 2005 three environmental groups filed a motion with the Federal Energy Regulatory Commission urging federal officials to require that the dam's emergency spillway be armored with concrete, rather than remain as an earthen spillway and that it did not meet modern safety standards. "In the event of extreme rain and flooding, fast-rising water would overwhelm the main concrete spillway, then flow down the emergency spillway, and that could cause heavy erosion that would create flooding for communities downstream, but also could cause a failure, known as 'loss of crest control.'" FERC and water agencies responsible for the **cost of the upgrades said it was unnecessary and concerns were overblown.**[26][27]*

**In 2006, a senior civil engineer sent a memo to his managers stating** "The emergency spillway meets FERC's engineering guidelines for an emergency spillway," and that "The guidelines specify that during a rare flood event, **it is acceptable for the emergency spillway to sustain significant damage.**"[28]

## **Spillway inspections**

The spillway cracked in 2013. A Senior Civil Engineer with the Department of Water Resources was interviewed by the Sacramento Bee and explained, **“It’s common for spillways to develop a void because of the drainage systems under them”** and **“There were some patches needed and so we made repairs and everything checked out.”**[29]

In July 2015, the state Division of Safety of Dams inspected the dam visually *"from some distance."*[30]



[end quotes]

The **[American Resistance Party](#)** says, **“If you look at the photo (above) of the big hole/crack in the main spillway... where is the rebar? Cast iron rebar was used in concrete as far back as the 18th century. But absolutely NO REBAR can be seen in the damaged main spillway hole! And the concrete appears to be only about 2-3 feet thick!”**

The responsibility of the Oroville Dam crisis can be laid directly on the head of Mr. Moonbeam Jerry Brown. (He cannot be governor for a 3<sup>rd</sup> & 4<sup>th</sup> term according to the California Constitution!) (And Brown hid the 2008 ineligibility of BHO for POTUS too!)

**California's troubled Oroville Dam wasn't on Gov. Brown's infrastructure 'wish list'**  
**<http://www.cnbc.com/2017/02/13/californias-oroville-dam-wasnt-on-browns-infrastructure-wish-list.html>**

###

Permission to reprint in whole or in part is gladly granted, provided full credit is given.